



TECHNICAL DATA SHEET

CROSS LOW

Walking shoes

Article NO: G3297

Upper: softshell
Outsole: phylon/TPR

Size: 36 - 48
Colour: black



Softshell shoes, black colour, reflective details.

This product is not a PPE (personal protective equipment), so it is not a subject of certification and it can not be marked by CE.

Pairs in carton: 10
Carton weight: 8,70 kg
Carton size: 0,090 m³

The shoes have to be perfect as for from and size, because they have rigid parts. The right size has to be found by measuring practically and carefully the shoes. The closing system has to be used correctly. The laces have to be tightened well without leaving too long free tops. The shoes have to be cleaned and treated with right, specific products, following the instructions for use. Do not keep footwear near heatings when not used and let them dry in a windy or room temperature. Before wearing and when cleaned, the shoes have to be controlled in order to find out visible defects existing, like closing system function, outsole profile's water, possible damages, etc. To define the right type of footwear to wear in every environment, the possible dangers and the place/ environment have to be included (e.g. construction industry, high temperatures, etc.). The shoes have to be stored correctly, keeping them in the proper packing.
